

**Fire Sprinklers
Inspection****Date: Sep 03, 2021
8:53****Result: In-Office Approval**

Address 8318 120 St Unit 304
Unit 304, Sia Immigration Solutions Inc.
Permit Number 21-038992-000-00

Comment:

acceptance based on submission of sched CB from PEng
no inspections

News Bulletin:

1. Effective 1 August 2021, an Occupied Spaces Checklist is no longer required to schedule a site review for unoccupied new construction. A representative of the Plumbing Contractor must still be present at the time of attendance by a Plumbing Official. A Checklist continues to be required for spaces that are occupied before FINAL ACCEPTANCE or OCCUPANCY have been granted. Where a site review of occupied spaces is scheduled without the required Checklist, the Plumbing Official will immediately discontinue the inspection, a re-inspection fee will be charged and a Checklist will need to be submitted prior to rescheduling, along with the additional separate Checklist processing fee.
2. The Surrey Building Bylaw states that a site re-visit fee of \$207 will be imposed whenever a building review was called for and the work to be reviewed was not ready.